

Technical Service Bulletin

Bulletin #:	2006-001		Date:	20/10/06
Product:	Compressor	☐ Generator	∑ Tools ☐ Too	
Subject:	Chuck replacement procedure			
Models				
IR12PS, IR10F	Pγ			

Some chucks can break prematurely on the IR12 and IR10 pick hammers. This was identified as a temporary quality issue with the heat treatment. In case of failure the chuck must be replaced following this procedure.

Replacement parts CPN

Model	Chuck	Nozzle CPN	Plug CPN
IR12PS	22mm HEX	85042380	85042141
IR10PV	22IIIII TILA	85042638	85042687

Installation procedure

- 1. Disassemble the hammer
- 2. Mark the orientation of the hexagon against the cylinder!!!
- 3. Using a steel bar Ø 20-22 mm press out the plastic cylinder plug, ref. 5 on the assembly drawing. You will insert the steel bar from the front through the chuck and press on the piston to press out the plug.
- 4. Cut a 20 mm long piece of Ø 22 mm steel bar or 22 mm hex. bar from an used chisel as shown in blue on the drawing
- 5. Weld this cut piece on the front of the chuck as shown in red
- 6. Insert the steel bar Ø 20-22 mm into the cylinder from the back and over this bar to press out the chuck
- 7. Degrease thoroughly the cylinder and new chuck
- 8. Cover the new chuck with Loctite 601 on the outside
- 9. Press in the chuck in the cylinder. **Keep the orientation of the hexagon against** the cylinder!!!
- 10. Let the Loctite 24 hours to harden
- 11. Lubricate the piston with oil
- 12. Grease the new plastic cylinder plug (ref. 5 on the assembly drawing) and press it into the cylinder. The plug must be replaced with a new one!
- 13. Assemble the hammer

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Revised (10-12)



Technical Service Bulletin

