

# Service Letter

*Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.*

**Bulletin:** 40007  
**Date:** 29 May 2009 Revised (10-12)  
**Product:** Compressors  
**Subject:** 7/41 Wiring harness and battery cable routing/protection

## APPLY'S TO:

MODELS	SERIAL NUMBER
7/41	418800 → 426380

## PROBLEM DESCRIPTION:

Battery cable and harness have not been routed correctly on some compressors which can lead to a shortcircuit and possible damage to attached components.

## Parts

QTY.	P/N	DESCRIPTION
1 m	22605117	Plastic conduit
4	92281427	Tie wraps


## INSTALLATION INSTRUCTIONS:

Our solution involves a simple repositioning and clamping of the cables to insure they do not come into contact with any other part which might otherwise inflict damage.

## WARNING


Isolate battery connection to avoid inadvertent strapup of the compressor while carrying out maintenance work.

Figure 1




1. Turn clamp (item 1) from original position to same as shown. **[Figure 1]**
2. Add tie wraps (item 2) in order to secure both conduits. **[Figure 1]**

Figure 2



3. Route conduits **[Figure 2]** and secure with one tie wrap (item 3).

**Figure 3**



4. Turn clamp (item 4) from original position to same as shown. **[Figure 3]**
5. Add tie wrap (item 5). **[Figure 3]**
6. Reconnect battery cables and run the unit.
7. Thoroughly check if the rerouting was carried out correctly.

**IMPORTANT INFORMATION:**

Warranty claims will be accepted for the above inspection and repair, allowing:

1. 1 hour labour for inspection and repair.
2. Travel and mileage according to current warranty reimbursement rules.