

Portable Power

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

PC-12-13
July 15, 2003
Revised (10-12)

GENSETS

SUBJECT: Damaged wires & insulation exiting Alternator J Box

MODELS AFFECTED: G20 through G40

SYMPTOMS: Excessive wear or shorting of wiring exiting J box on the Alternator

CAUSE: Loose or improperly routed wire through J box

REMEDY: Every 1000 hours of operation, check wiring inside J box to assure wires are secure and exhibit no wear due to rubbing contact.

ACTION: Secure and reroute all loose or rubbing wires in J box, with zip ties or other proper mounting hardware. Replace any damaged wire, or any wire with damaged insulation.