


























TSB INDEX

General

-  PC-1-000 - May 6, 2003 Cancels PC-1-000 dated 9-28-99 - GENERAL INDEX
-  PC-1-001 - August 4, 1980 - SPEED AND PRESSURE REGULATORS
-  PC-1-002 - August 4, 1980 - SHUTDOWN OF ENGINE
-  PC-1-003 - August 4, 1980 - DESIGN CHANGES
-  PC-1-004 - 10-10-84, (Cancels PC-1-84, Dated 1-27-81) - BREATHING AIR COMPRESSORS
-  PC-1-005 - February 12, 1981 - CIRCUIT BOARD OPERATION
-  PC-1-006 - 3/24/81 - CHANGING CIRCUIT BOARDS
-  PC-1-007 - 3/24/81 - SERVICE LITERATURE FORMS
-  PC-1-008 - 8/31/83 Cancels PC-1-008, Dated 3/24/81 - SERIAL NUMBERING SYSTEM
-  PC-1-009 - April 29, 1981 - OIL FILTER ELEMENT
-  PC-1-010 - June 1, 1981 - RECOMMENDED WHEEL BEARING MAINTENANCE AND LUBRICATION PROCEDURES
-  PC-1-011 - June 1, 1981 - DESIGN CHANGES
-  PC-1-012 - 6-10-85, Cancels PC-1-012 dated May 28, 1982. - HIGH PRESSURE AIREND PRECAUTIONARY MEASURES
-  PC-1-013 - August 19, 1981 - SERVICE LITERATURE
-  PC-1-014 - August 19, 1981 - OIL SEPARATOR ELEMENT GROUNDING
-  PC-1-015 - 7-18-83 - UPDATE - Compressor Airend Design Change to Incorporate New Style Oil Seal
-  PC-1-016 - 4-24-86 - WARRANTY REGISTRATION .
-  PC-1-017 - March 15, 1982 - Universal Voltage Filter on P-300, P-335 and P-425
-  PC-1-018 - March 16, 1982 - Design Changes
-  PC-1-019 - March 8, 1983 (Cancels PC-1-0, dated 5-27-82) - EXCESSIVE OIL CARRY-OVER
-  PC-1-020 - 3-14-89 (PC-1-020, Sheets 1 thru 6, dated June 25, 1982, are superseded by those dated 3-14-89) - INFORMATION FOR MAJOR CHANGES
-  PC-1-021 - 09-20-89 (This sheet cancels PC-1-021 dated August 6, 1982) - SAFETY SHUTDOWN SYSTEMS
-  PC-1-022 - August 9, 1982 - METHODS TO ELIMINATE NEW MACHINE INVENTORY START-UP PROBLEMS
-  PC-1-023 - September 1, 1982 - New Publication - "AIREND REPLACEMENT PROCEDURES", Form No. 35352731 - for Screw Air Ends Shipped from Mocksville Plant
-  PC-1-024 - October 15, 1982 - NEW FRONT SEAL ON 226 MM AIRENDS

TSB INDEX

- ☐ PC-1-025 - October 15, 1982 - OIL FILLER PLUG
- ☐ PC-1-026 - October 26, 1982 - MODEL P-300/335/425/450 OIL LINE RESTRAINT
- ☐ PC-1-027 - Air End Failures Warranty or Exchange
- ☐ PC-1-028 - March 7, 1983 - WAX TREATMENT/REMOVAL
- ☐ PC-1-029 - 04-14-83(Cancels PC-1-02 dated 03-30-83) - IMPROVED SEALING AT FRONT OIL SEAL
- ☐ PC-1-030 - 07-29-91 (Cancels PC-1-030 Dated 05-31-83) - AIR CLEANER SERVICE AND ACCESSORIES FOR EXTENDED LIFE
- ☐ PC-1-031 - 12/21/83 - Compressor Oil Filter Piping
- ☐ PC-1-032 - 3-05-84 - LIQUID GASKET MATERIALS
- ☐ PC-1-033 - 10-10-84 (Cancels PC-1-033 Dated: 4-10-84) - OIL FILTER INDICATORS

- ☐ PC-1-034 - 6-04-84 - ENGINE TEMPERATURE SWITCH
- ☐ PC-1-035 - 3-9-89 (This sheet cancels PC-1-035 dated 6-20-84) - COMPLAINT OF 2-WAY VALVE ("Service Air" Button) RESETTNG TO "START POSITION" DURING RUN MODE
- ☐ PC-1-036 - 10-4-84 - ANTI-RUMBLE VALVE OPERATION
- ☐ PC-1-037 - 5-6-85 - NEW STYLE (PLUG-IN) FUSE
- ☐ PC-1-038 - 7-11-86 (This sheet cancels PC-1-038 dated 11-15-85) - CHANGE DISCHARGE HOSE CLAMPS
- ☐ PC-1-039 - 12-19-85 - DEXON ® II ATF AS FACTORY FILL FOR ENTIRE PORTABLE LINE
- ☐ PC-1-040 - 7-11-86 - SERVICE LITERATURE HANDLING
- ☐ PC-1-041 - 7-11-86 - DISCHARGE CHECK VALVE ON LARGE PORTABLES AND OIL FIELD UNITS
- ☐ PC-1-042 - 08-08-86 - INOPERATIVE INSTRUMENT "FAULT" LAMPS
- ☐ PC-1-043 - 09-24-86 - DIXSON TACHOMETERS
- ☐ PC-1-044 - 3-13-89 - IMPROVED 2-WAY VALVE/PRESSURE REGULATOR - Across-The-Board Application
- ☐ PC-1-045 - 03-20-89 - BATTERY DRAINED ON GASOLINE ENGINES - On Mocksville Manufactured Units
- ☐ PC-1-046 - 04-20-89 - SPACERS IN AIREND SEALS
- ☐ PC-1-047 - 12-16-92 (Revised) - DRIVE COUPLING FAILURE AND/OR EXCESSIVE UNIT VIBRATION
- ☐ PC-1-048 - 09-11-91 - Mounting of LRG (Less Running Gear) portable and Utility Style compressors Mocksville Built Units
- ☐ PC-1-049 - 10-01-91 - FREE SAFETY WARNING DECALS ANY IR PORTABLE COMPRESSOR
- ☐ PC-1-050 - 06-02-92 - CHEMICAL CORROSION DAMAGE

TSB INDEX

- ☐ PC-1-051 - 08-31-92 - New Serial Number System/Plate
- ☐ PC-1-051A - 11-19-92 - MOCKSVILLE SERIAL NUMBER SYSTEM
- ☐ PC-1-052 - May 19, 1993 - DRIVE COUPLING INSTALLATION
- ☐ PC-1-053 - 08-23-93 - FOR INFORMATION ONLY
- ☐ PC-1-054 - 8-23-93 - Mocksville Serial Number Systems
- ☐ PC-1-055 - 04-21-95 - Drive Couplings
- ☐ PC-1-056 - April 11, 1994 - Safety Decals, FOR INFORMATION ONLY
- ☐ PC-1-057 - Standard Capscrew Torque Specification, FOR INFORMATION ONLY
- ☐ PC-1-058 - June 15, 1994 - NEW MACHINE MODEL - FOR INFORMATION ONLY
- ☐ PC-1-059 - August 4, 1994 - MODEL NOMENCLATURE CHANGE INFORMATION ONLY
- ☐ PC-1-060 - June 28, 1994 - Thermal Fuses
- ☐ PC-1-061 - October 20, 1995 - New Service Literature Format Update
- ☐ PC-1-062 - February 26, 1996 - Information Only
- ☐ PC-1-063 - 9-25-96 - Incorrect Air Filter Restriction Indicators
- ☐ PC-1-064 - 9-25-96 - Replacing Acoustic Foam Panels in Portable Products
- ☐ PC-1-065 - 10-15-96 - Tampering with Certified Engines
- ☐ PC-1-066 - July 9, 1998 - Products Operation, Maintenance and Parts Manuals Serial Numbers
- ☐ PC-1-067 - May 6, 2003 Replaces PC1-067 dated 9/16/99 - Portable Compressor Fluid Chart
- ☐ PC-1-068 - May 6, 2003 - Ingersoll-Rand Compressor Fluids
- ☐ PC-1-069 - May 6, 2003 - CONDENSATE DRAIN MAINTENANCE FOR ALL INSTRUMENT QUALITY (IQ) SYSTEMS AND OIL FREE SYSTEMS

☐ Rotary Vane

- ☐ PC-3-001 - 3/24/81 - RR85: SHIMMING PROCEDURE FOR ROTOR END CLEARANCE

☐ XL Model

TSB INDEX

☐ PC-4-001 - 6-04-84 - SPECIAL OIL COOLER COATING - Mocksville Manufactured Portable Compressors

TSB INDEX

- ☐ **P-XP-HP 0-400 CFM**
 - ☐ **PC-5-001 - October 28, 1980 - OIL FILTERS**
 - ☐ **PC-5-002 - December 4, 1980 - ENGINE OIL CAPACITY, CHANGE INTERVAL AND ENGINE OIL COOLER**
 - ☐ **PC-5-003 - December 9, 1980 - FAN HUB FAILURES**
 - ☐ **PC-5-004 - February 3, 1981 - STARTER PROTECTION KIT**
 - ☐ **PC-5-005 - February 3, 1981 - STARTER PROTECTION KIT**
 - ☐ **PC-5-006 - February 3, 1981 - STARTER PROTECTION KIT**
 - ☐ **PC-5-007 - March 16, 1982 - Cancels PC-5-007 dated 2/24/82 - DRIVE COUPLING ARRANGEMENT - PORTABLE AIR COMPRESSORS**
 - ☐ **PC-5-008 - 3/23/81 - DRAWBARS ON MOCKSVILLE MANUFACTURED PORTABLES**
 - ☐ **PC-5-009 - 3/24/81 - DRAWBARS ON MOCKSVILLE MANUFACTURED PORTABLES**
 - ☐ **PC-5-010 - 3/24/81 - BLOWDOWN ORIFICE - MOCKSVILLE MANUFACTURED PORTABLES**
 - ☐ **PC-5-011 - 3/24/81 - AIREND OIL SEALS MOCKSVILLE MANUFACTURED PORTABLES**
 - ☐ **PC-5-012 - 3/24/81 - COLD WEATHER STARTING HINTS - MOCKSVILLE MANUFACTURED PORTABLES**
 - ☐ **PC-5-013 - 4/15/81 - Cancels PC-5-013 Dated 3/24/81 - OIL BLOWBACK INTO AIR FILTER UPON SHUTDOWN MOCKSVILLE MANUFACTURED PORTABLES**
 - ☐ **PC-5-014 - Sept. 16, 1981 - Design Changes in Mocksville Manufactured Units.**
 - ☐ **PC-5-015 - January 7, 1982 - Mocksville Manufactured Units**
 - ☐ **PC-5-016 - March 17, 1982 - FUEL SOLENOID CONNECTOR**
 - ☐ **PC-5-017 - March 17, 1982 - DRIVE PLATE BOLTS**
 - ☐ **PC-5-018 - May 23, 1982 - Oil Scavenge Tube for Vertical Separator Element**
 - ☐ **PC-5-019 - 04-22-83 - INSTALLATION REQUIREMENTS FOR UTILITY PACKAGES**
 - ☐ **PC-5-020 - 6/13/83 - GAUGE KIT OPTION**
 - ☐ **PC-5-021 - 3-05-84 - FAN SHAFT SEAL**
 - ☐ **PC-5-022 - 3-05-84 - FAN IDLER ARRANGEMENT**
 - ☐ **PC-5-023 - 6-04-84 - SONIC ORIFICE INSTALLATION**
 - ☐ **PC-5-024 - 6-04-84 - OIL COOLER MOUNTING TABS**

TSB INDEX

- ☐ PC-5-025 - 6-20-84 - OPERATING & MAINTENANCE MANUAL
- ☐ PC-5-026 - 9-27-84 - DRIVE COUPLING CHANGES
- ☐ PC-5-027 - 10-15-84 - P-160/175/185 and 375 FRONT SHAFT SEAL
- ☐ PC-5-028 - 12-19-85 Cancels Sheet PC-5-028 Dated 3-4-85 - EXCESSIVE OIL CARRY-OVER
- ☐ PC-5-029 - 4-17-86 - INSTALLATION INSTRUCTIONS FOR IMPROVED OIL SEALS
- ☐ PC-5-030 - 7-11-86 - DRIVE COUPLING LOCATION
- ☐ PC-5-031 - 7-11-86 - CHANGE OF SPRING IN OIL COOLER CHECK VALVE
- ☐ PC-5-032 - 7-30-87 - STIFF OR SQUEAKY TORSION AXLE
- ☐ PC-5-033 - 02-16-90 - FAILED DRIVE COUPLING
- ☐ PC-5-034 - 3-9-89 - FAILED DRIVE COUPLING
- ☐ PC-5-035 - 3-9-89 - SERVICE PARTS FOR PUSH SOLENOID DEUTZ-POWERED
- ☐ PC-5-036 - 12-16-92 Revised - WIRING HARNESS DAMAGE
- ☐ PC-5-037 - 06-22-90 - PRESSURE DROPS WHEN UNIT IS RUNNING
- ☐ PC-5-038 - 03-11-91 Revised: 04-19-91 This Sheet Cancels PC-5-038 dated 3-11-91 - PREVENT ENGINE STARTER DAMAGE/EASIER COLD STARTING
- ☐ PC-5-039 - 03-11-91 - DRIVE COUPLING FAILURES
- ☐ PC-5-040 - 3-25-91 - Mounting of LRG (Less Running Gear) Portable and Utility Style Compressors Mocksville Built Units
- ☐ PC-5-041 - 10-15-91 - POSITIVE BATTERY CABLE ROUTING
- ☐ PC-5-042 - 10-22-91 - REFLECTORS AS STANDARD ON NEW "PRESTIGE" SERIES
- ☐ PC-5-043 - 11-04-91 Revised 11-12-91 (This cancels sheet dated 11-04-91) - "WYE" SERVICE VALVES ON "PRESTIGE" SERIES ALL MOCKSVILLE MANUFACTURED UNITS
- ☐ PC-5-044 - 01-13-92 - PRESTIGE SERIES (85 mm AIREND) REGULATION PROBLEMS
- ☐ PC-5-045 - 06-01-92 - FREEZING / ICING OF REGULATION SYSTEM SMALL and MID-SIZE - MOCKSVILLE BUILT UNITS
- ☐ PC-5-046 - 11-5-92 - AIREND DRIVE COUPLING FAILURE
- ☐ PC-5-047 - 05-19-93 - "OXYGENATED" GASOLINE
- ☐ PC-5-048 - 08-23-93 - ENGINE SPEED AND REGULATION OPERATION
- ☐ PC-5-049 - July 19, 1994 - OPERATING, MAINTENANCE & PARTS MANUAL
- ☐ PC-5-050 - February 2, 1995 - JOHN DEERE ENGINE WATER PUMP SEAL

TSB INDEX

- ☐ PC-5-051 - December 22, 1994 - ALTERNATORS IN JOHN DEERE ENGINES
- ☐ PC-5-052 - October 13, 1995 Revised - ALTERNATORS ON JOHN DEERE 3 AND 4 CYLINDERS ENGINES - Reference: TSB PC-5-051
- ☐ PC-5-053 - October 9, 1995 - PRODUCT SAFETY BULLETIN
- ☐ PC-5-054 - January 18, 1996 - Portable Compressors equipped with Push Button Start/Run Valves
- ☐ PC-5-055 - May 1, 2000 replaces sheet dated 4/3/97 - 100-185 CFM AIREND WARRANTY PERIOD (INFORMATION ONLY)
- ☐ PC-5-056 - September 25, 1997 update - ENGINE SPEED CONTROL
- ☐ PC-5-057 - September 25, 1997 - BROKEN GAUGE CLIPS
- ☐ PC-5-058 - September 25, 1997 - BROKEN CORNER TABS
- ☐ PC-5-059 - September 25, 1997 - LEAKING RADIATOR
- ☐ PC-5-060 - October 27, 1997 - HOT STARTING
- ☐ PC-5-061 - July 20, 1998 - BROKEN ISOLATOR BOLT
- ☐ PC-5-062 - July 30, 1998 - WATER IN COMPRESSOR OIL
- ☐ PC-5-063 - September 4, 1998 Revised - DRIVE COUPLINGS
- ☐ PC-5-064 - September 2, 1999 - UTILITY COMPRESSORS FAN DRIVE
- ☐ PC-5-065 - December 13, 1999 - ENGINE SPEED CONTROL

☐ P-XP-HP 401-700 CFM

- ☐ PC-6-001 - August 4, 1980 - AIR END OVERHEATING
- ☐ PC-6-002 - 3/24/81 - GM DESIGN CHANGES MOCKSVILLE MANUFACTURED PORTABLES
- ☐ PC-6-003 - October 11, 1995 - SPECIAL MOUNTING INSTRUCTIONS FOR PORTABLE COMPRESSORS (Less Running Gear or with Running Gear Removed)

☐ P-XP-HP 701 and above CFM

- ☐ PC-7-001 - August 4, 1980 - AIR CLEANER ASSEMBLIES
- ☐ PC-7-002 - September 9, 1980 - AIR END FAN DRIVE SHAFT SEAL
- ☐ PC-7-003 - Sept. 16, 1981 - OPERATING TEMPERATURE AND OIL CHANGE INTERVAL

TSB INDEX

- ☐ PC-7-004 - January 12, 1982 - COMPRESSOR OIL FILTERS ON MOCKSVILLE MANUFACTURED UNITS.
- ☐ PC-7-005 - 8-8-83 - Front Seal Oil Supply Line - Mocksville Manufactured Units
- ☐ PC-7-006 - 9-25-85 - BROKEN AIR CLEANER MOUNTING BANDS - on Mocksville Manufactured Units
- ☐ PC-7-007 - 7-11-86 - RADIATOR VENTING - Mocksville Manufactured Units
- ☐ PC-7-008 - 7-11-86 - ENGINE OPERATING TEMPERATURES - Mocksville Manufactured Units
- ☐ PC-7-009 - 9-14-87 (This sheet cancels sheet dated 4-6-87) - DISCHARGE PIPING CHANGES ON MOCKSVILLE Manufactured Units
- ☐ PC-7-010 - 4-6-87 - HARD STARTING PROBLEM - on Mocksville Manufactured Units
- ☐ PC-7-011 - 9-30-87 (This sheet cancels sheet dated 7-30-87) - START-RUN VALVE - (2-WAY VALVE) - Mocksville Manufactured Units
- ☐ PC-7-012 - 3-16-88 - POTENTIAL FAULTY OIL TEMPERATURE BYPASS VALVE - on Mocksville Built Units
- ☐ PC-7-013 - 3-16-88 (Please cancel PC-7-013, moved to PC-8) - PLUGGED OIL GALLEYS IN AIREND - on Mocksville Built Units
- ☐ PC-7-014 - 12-16-92 (Revised) - SAFETY VALVE PIPING ON LARGE DETROIT DIESEL POWERED UNITS - Mocksville Built Units
- ☐ PC-7-015 - 09-10-93 (Revised) - SEPARATOR TANK AIR TEMPERATURE SHUTDOWN ON LARGE DETROIT DIESEL POWERED UNITS - Mocksville Built Units
- ☐ PC-7-016 - 12-16-92 (Revised) - AIR END OIL LINE PIPING ON LARGE DETROIT DIESEL POWERED UNITS Mocksville Built Units
- ☐ PC-7-017 - 12-16-92 (Revised) - AIR END OIL LINE PIPING ON LARGE CUMMINS DIESEL POWERED UNITS - Mocksville Built Units
- ☐ PC-7-018 - 12-07-89 - RELOCATION OF PRESSURE RELIEF VALVE on HR-2 AIREND - on Mocksville Built Units
- ☐ PC-7-019 - 07-17-91 (This sheet cancels PC-7-019 dated 4-24-90) - COMPRESSOR OIL LEVEL ON LARGE CUMMINS AND CAT POWERED UNITS - Mocksville Built Units
- ☐ PC-7-020 - 12-16-92 (Revised) - HARD STARTING OR IMMEDIATE SHUTDOWN ON LARGE CUMMINS POWERED COMPRESSORS - Mocksville Built Units
- ☐ PC-7-021 - 12-16-92 (Revised) - LEAK IN SERVICE (DISCHARGE) PIPE ON LARGE CUMMINS/CAT POWERED UNITS - Mocksville Built Units
- ☐ PC-7-022 - 09-19-90 - NEW DRIVE COUPLING FOR HP-1000 thru P-1600-W-CU - on Mocksville Built Units
- ☐ PC-7-023 - 01-31-91 - OIL PUMP KIT RELEASED FOR HP-1300B/XP-1400B/P-1600B-W-GM AIRENDS - MOCKSVILLE BUILT UNITS
- ☐ PC-7-024 - 02-01-91 - BLOWN FUSE ON START-UP ON LARGE EPA UNITS - Mocksville Built Units
- ☐ PC-7-025 - 03-05-91 - UNUSUAL AUTOMATIC SHUTDOWN ON FASTRACK AND LARGE EPA UNITS FAMILY MOCKSVILLE-BUILT UNITS
- ☐ PC-7-026 - 11-19-91 - 226 mm AIREND DRIVESHAFT BEARING INSTALLATION - ALL MOCKSVILLE MANUFACTURED UNITS
- ☐ PC-7-027 - 08-23-93 - LARGE PORTABLE COMPRESSORS IN SNOWMAKING APPLICATIONS

TSB INDEX

- ☐ PC-7-028 - April 11, 1994 - NXP LOW BATTERY CONDITION
- ☐ PC-7-029 - June 15, 1994 - ENGINE OIL PRESSURE SWITCH FAILURES ON FASTRACKS
- ☐ PC-7-030 - September 9, 1996 - FIRE HAZARD CAUSED BY LEAKING ENGINE EXHAUST ELBOW
- ☐ PC-7-031 - September 9, 1996 - ENGINE TEMPERATURE GAUGE READINGS
- ☐ PC-7-032 - October 9, 1996 - FOAM PANELS IN KIT 36036119
- ☐ PC7-034 IQ FILTERS

TSB INDEX

☐ XHP

- ☐ PC-8-000 - May 6, 2003 Cancels PC-8-000 dated 09-28-99 - XHP INDEX
- ☐ PC-8-001 - August 4, 1980 - AIR CLEANER ASSEMBLIES
- ☐ PC-8-002 - August 4, 1980 - FIELD REPLACEMENT OF AIR ENDS
- ☐ PC-8-003 - October 15, 1982 - FRONT SEAL AIR SUPPLY - On Mocksville Manufactured Units
- ☐ PC-8-004 - May 6, 2003 - COMPRESSOR FLUID FOR XHP PORTABLE COMPRESSORS
- ☐ PC-8-005 - 7-11-86 - COMPRESSOR OIL FOR XHP OIL FIELD PACKAGES - On Mocksville Manufactured Units
- ☐ PC-8-006 - 1-21-87 - OIL STRAINER ELEMENT MAINTENANCE - for Mocksville Manufactured Units
- ☐ PC-8-007 - 6-28-88 (Moved from PC-7 to PC-8) - PLUGGED OIL GALLEYS IN AIREND
- ☐ PC-8-008 - 05-26-93 - HR2 (XHP) AIREND "BURP" OR OVERHEATING ANY XHP PORTABLE COMPRESSOR MOCKSVILLE BUILT UNITS
- ☐ PC-8-009 - 01-13-93 (Revised) - VENTING OF INTERSTAGE RELIEF VALVE ANY XHP PORTABLE COMPRESSOR SO EQUIPPED MOCKSVILLE BUILT UNITS
- ☐ PC-8-010 - 03-17-93 - HR2 (XHP) AIREND BEARING OIL TUBE FAILURE ANY XHP PORTABLE COMPRESSOR MOCKSVILLE BUILT UNITS
- ☐ PC-8-011 - July 1, 1997 (Revised) - HR2 AIREND STEEL TUBING
- ☐ PC-8-012 - August 12, 1996 - Rotary Shaft Seal on HR2 Airend
- ☐ PC-8-013 - April 4, 1997 - FIRE HAZARD CAUSED BY LEAKING ENGINE EXHAUST ELBOW
- ☐ PC-8-014 - April 3, 1998 - XHP AIREND (HR2) SHAFT SEAL
- ☐ PC-8-015 - July 1, 1998 - DISCHARGE HOSE
- ☐ PC-8-016 - May 6, 1999 - FAN CONTACT TO ORIFICE RING
- ☐ PC-8-017 - May 6, 1999 - PRESSURE REDUCING VALVE ON CUSTOMER 1 PRODUCTS
- ☐ PC-8-018 - May 6, 1999 - COLD WEATHER OPERATION OF HYDRAULIC DRIVEN FANS
- ☐ PC-8-019 - July 15, 1999 - SCAT OIL COOLING AND AIR AFTER COOLING SYSTEMS
- ☐ PC-8-020 - May 6, 2003 - XHP505 COMPRESSOR FLUID TO BE REPLACED

TSB INDEX

☐ Engines

- ☐ PC-9-001 - 3/23/81 - WHITE G1600 ENGINE TIMING PROCEDURE MOCKSVILLE MANUFACTURED PORTABLES
- ☐ PC-9-002 - January 12, 1982 - DETROIT DIESEL ENGINE SHUTDOWN SOLENOID PROBLEMS ON MOCKSVILLE MANUFACTURED UNITS.
- ☐ PC-9-003 - June 25, 1982 Cancels PC-5-019 dated 6/4/82 - CARBURETOR FLOODING OF WHITE ENGINE POWERED PORTABLE COMPRESSORS - on Mocksville Manufactured Units
- ☐ PC-9-004 - August 9, 1982 - JOHN DEERE ENGINE WARRANTY REVISIONS - on Mocksville Manufactured Units
- ☐ PC-9-005 - 05-06-83 - FUEL AND LUBE OIL - DETROIT DIESEL ALLISON ENGINES - All Mocksville Manufactured Units
- ☐ PC-9-006 - 7-24-84 - NEW CATERPILLAR ENGINE DELIVERY RECORD on all Mocksville Manufactured Caterpillar Powered Units
- ☐ PC-9-007 - 10-8-84 Cancels PC-9-007 Dated 9-27-84 - JOHN DEERE POWERED PORTABLE COMPRESSORS - Manufactured In Mocksville, North Carolina
- ☐ PC-9-008 - 6-14-85 - NEW WATER PUMP SHAFT FOR CUMMINS L-10 ENGINE - On Mocksville Manufactured Units
- ☐ PC-9-009 - 9-23-85 - GREATER ENGINE OIL CAPACITY - Mocksville Manufactured Units
- ☐ PC-9-010 - 10-27-85 - COLD STARTING RECOMMENDATIONS - for Mocksville Manufactured Units
- ☐ PC-9-011 - 7-11-86 - AFTERCOOLER VENTING - for Mocksville Manufactured Units
- ☐ PC-9-012 - 4-27-87 - CUMMING ENGINE WARRANTY FORM 35327899 - On Mocksville Manufactured Units
- ☐ PC-9-013 - 6-11-87 - NEW BUSHING FOR ALTERNATOR DRIVE SHEAVE - On All Mocksville Manufactured Units
- ☐ PC-9-014 - 9-21-87 - P-185A-W-JD ENGINE OVERHEATING - On Mocksville Manufactured Units
- ☐ PC-9-015 - 2-26-88 - POTENTIAL ENGINE DAMAGE - Ford Powered Compressors - Mocksville Manufactured Units
- ☐ PC-9-016 - 11-21-88 - IGNITION TIMING FOR FORD GASOLINE ENGINES - Mocksville Built Units
- ☐ PC-9-017 - 02-16-90 - DIFFICULT RESTARTING OF HOT UNIT - P-130A/P-160A/P-185B-W-JD - On Mocksville Built Units
- ☐ PC-9-018 - 06-22-90 - DIFFERENT (Delco - Bosch) ALTERNATORS ON DEUTZ AND SOME CUMMINS-POWERED MACHINES - Mocksville Built Units - (March - May 1990)
- ☐ PC-9-019 - 09-19-90 - CUMMINS - NEW ENGINE INSPECTION ON XP-600 THRU P-1600-W-CU - on Mocksville Built Units
- ☐ PC-9-020 - 09-28-90 - DEFECTIVE DEUTZ FUEL SOLENOID - on P-100D/125D-W-D Mocksville Built Units
- ☐ PC-9-021 - 10-24-90 - ENGINE COOLANT LEAK ON P-185B-W-JD - on Mocksville Built Units
- ☐ PC-9-022 - 10-18-93 - JOHN DEERE ENGINE WARRANTY REGISTRATION

TSB INDEX

- ☐ PC-9-023 - December 9, 1994 - JOHN DEERE ENGINE WARRANTY REGISTRATION
- ☐ PC-9-024 - December 16, 1996 - ENGINE CYLINDER LINER CAVITATION
- ☐ PC-9-025 - October 27, 1997 - ENGINE FAILURE DUE TO LOSS OF OIL PRESSURE

TSB INDEX

☐ Service Topics

- ☐ PC-10-000 - May 6, 2003 Replaces Index dated December 4, 1998 - Service Topics Index
- ☐ PC 10-001 - May 6, 2003 Replaces PC 10-001 dated 12/4/98 - EXTENDED LIMITED AIR END WARRANTY

☐ Product Training

- ☐ PC-11-000 - May 6, 2003 Cancels PC11-000 dated 11-26-01 - PRODUCT TRAINING INDEX
- ☐ PC 11-001 - May 6, 2003 Replaces PC 11-001 dated 1-10-92 and cancels PC 11-002 dated 01-10-92 - Portable Power & Power Generation 2003 Training Guide
- ☐ PC-11-002 - 01-10-92 CANCELS PC-11-002 DATED: 01-23-91 - 1992 TRAINING SCHEDULE
- ☐ PC-11-003 - 10-08-93 Cancels sheet dated 01-23-92 - TRAINING PROGRAMS
- ☐ PC-11-004 - 10-08-93 Cancels sheet dated 06-27-88 - AIREND OVERHAUL MANUALS
- ☐ PC-11-005 - 11-25-91 - HR - 2, AIREND REBUILD SCHOOL

☐ Gensets

- ☐ PC-12-000 - May 6, 2003 Cancels PC12-000 dated Sept. 4, 2002 - GENSET INDEX
- ☐ PC-12-001 - 06-21-88 - BATTERY DRAIN ON GENSET E-20-W-JD Units PRIOR TO S/N 167877 - on Mocksville Built Units
- ☐ PC-12-002 - 12-13-89 - ADJUSTMENTS AFTER REPLACING VOLTAGE REGULATOR BOARD - on Mocksville Built Units - E-20-W-JD, E-30-W-CU and E-5U-W-CU Gensets
- ☐ PC-12-003 - 06-22-90 - STICKING INTERLOCK SWITCH on E-20-W-JD, E-30-W-CU and E-50-W-CU GENSETS - Mocksville Built Units
- ☐ PC-12-004 - 03-31-92 - FUEL LEAK ON L6 LIGHT TOWER All Mocksville Built Units
- ☐ PC-12-005 - 12-16-92 (Revised) - CRACKED EXHAUST MANIFOLDS/EXHAUST PIPES L8 LIGHT TOWERS Mocksville Built Units
- ☐ PC-12-006 - September 2, 1999 - ULTRA VIOLET RADIATION CAN CAUSE SERIOUS SKIN BURN AND EYE INFLAMATION
- ☐ PC-12-008 - May 6, 2003 - (GENSETS) FUEL CAPS NOT PROPERLY VENTED
- ☐ PC-12-009 - May 6, 2003 - MODULE FOUR CABLE STRAIN RELIEFS
- ☐ PC-12-010 - May 6, 2003 - (GENSETS) FUEL LEAKS AROUND FUEL GAUGE
- ☐ PC-12-011 - May 6, 2003 - (GENSETS) INCORRECT PARTS LISTINGS ON MITSUBISHI ENGINES

TSB INDEX

- ☐ PC12-19 Subject: Incorrect Fuel Solenoid Wiring
- ☐ PC12-20
- ☐ PC12-21 Subject: Broken Alternator Tie Rod Bolts
- ☐ PC12-23 Incorrect Tires and Wheels