

PC-1-039

September 16, 1999

Replaces PC1-039 dated 12/19/85

Compressor Fluid

Models affected: All portable compressors with operating pressures of 100 psi through 300psi (model prefixes P, XP, HP, VHP and some XHP)

Symptoms:

1. Excessive foaming of compressor fluid
2. Excessive oil carryover into service air

Cause: Dexron III has been found to be the source of the above symptoms on various machines.

Remedy: Use Ingersoll-Rand Pro Tec™ Compressor Fluid. All above models are factory filled with Pro Tec™ Compressor Fluid.

Pro Tec™ is available from the Mocksville Parts Department as follows:

5 gallon container	36899706
--------------------	----------

55 gallon container	36899714
---------------------	----------

275 gallon container (tote)	36899722
-----------------------------	----------

NOTE: Refer to TSB PC10-001 concerning extended airend warranty when using Ingersoll-Rand filters and fluids.

Refer to TSB PC-1-067 for current Portable Compressor fluid requirements.