

Portable Power

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

PC-12-008
May 6, 2003
Revised (10-12)

(GENSETS) FUEL CAPS NOT PROPERLY VENTED

MODELS AFFECTED: G8 through G575

SYMPTOMS: Fuel leaking around fittings, over pressurization,
Excessive cap back pressure.

CAUSE: Lack of proper tank ventilation

REMEDY: Replace Fuel Cap

ACTION: Order cap and replace.
P/N 85509222

Dispose of original cap locally.

Warranty claims will be accepted until September 1, 2003
for parts, labor, and freight.

Claims should refer to “CAMPAIGN 02-2”.