Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

PC-12-009 May 6, 2003 Revised (10-12)

MODULE FOUR CABLE STRAIN RELIEFS

MODELS AFFECTED: G50 through G575

SYMPTOMS: Mod 4 Can Bus fault will appear on unit display and cause a

shutdown.

CAUSE: Strain relief only offers one supporting screw, thus allowing cable

to lose contact with the CB12 and Can Bus.

REMEDY: Replace Strain Relief

ACTION: Order Strain Relief and replace.

Part No. 85626638

Dispose of original cap locally.

Warranty claims will be accepted until September 1, 2003 for

parts, labor, and freight.

Claims should refer to "CAMPAIGN 02-3".