

Portable Power

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

PC-12-12
July 15, 2003
Revised (10-12)

GENSETS

SUBJECT: Incorrect location of brake control wire on 6 way plug for trailers

MODELS AFFECTED: G20 through G575

SYMPTOMS: Brakes lock up even though tow vehicles brakes are not applied

CAUSE: Brake control wire located on wrong pin of six way plug

REMEDY: Install brake control wire to correct pin location in harness connector.

ACTION: Relocate connector wiring per the drawing below.

Trailer Connector 6-way Plug Wiring

