



Technical Service Bulletin

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Number: PC12-21

Date: January 17, 2005 **Revised (10-12)**

Subject: Broken Alternator Tie Rod Bolts

MODELS AFFECTED:

G170, G190

SYMPTOMS: Tie Rod bolts break.

CAUSE: Defective Tie Rods from supplier.

REMEDY: Replace Tie Rods with IR kit CPN 36095412.

WARRANTY ACTION: Claims will be accepted for 1.5 hrs labor and actual travel time. We will accept claims until 6-17-05. Reference CAMPAIGN 04-5 on claim.