



Technical Service Bulletin

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Number: PC12-22

Date: February 24, 2005 **Revised (10-12)**

Subject: Engine preglow setting incorrectly set in controller

MODELS AFFECTED:

G50-G600

SYMPTOMS: Hard starting in cold weather.

CAUSE: Engine preglow parameter set incorrectly.

REMEDY: Change Engine preglow parameter to "1" in Configuration menu, Factory submenu.

WARRANTY ACTION: NONE. INFORMATION ONLY. THIS IS NOT A CAMPAIGN.