



Technical Service Bulletin

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Number: PC12-030

Date: Dec. 5, 2006 **Revised (10-12)**

Subject: Incorrectly installed spring inside of Air Intake Hose

MODELS AFFECTED:

Models	Serial Number Range
G125 Powersource	367047 to 375986

The above models were fitted with a spring inside the Air Intake Pipe leading to the turbo from the air filter assembly.

SYMPTOMS:

Spring inside air intake pipe.

REMEDY:

Remove Air Intake Pipe and remove spring, replace pipe. We will allow 1 hour labor to make the repair and reasonable travel time.

Submit warranty and reference CAMPAIGN NUMBER 06-12 for this repair. Destroy all springs. Claims will be accepted until July 1, 2007.