



### Technical Service Bulletin

*Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.*

**Number:** PC12-037

**Date:** July 5, 2007

**Revised (10-12)**

**Subject:** Main power wiring to breaker in main breaker enclosure

**Symptoms:** Circuit and component failures caused by wire abrasion.

**Models Affected:**

G40B	G60	G80A	G125
Serial # Break	Serial # Break	Serial # Break	Serial # Break
381019	378489	232242	377356

**Remedy:**

Reroute and secure wiring per instructions included in kit 23103526.

**Warranty:**

Warranty claims will be accepted for the kit and 4 hours labor per machine until January 1, 2008. Claim must reference Campaign number 07-1.