Technical Service Bulletin



Number: PC13-003

Date: January 4, 2007 Revised (10-12)

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

PRODUCT IMPROVEMENT WL350 and WL440 ENTRY STEPS

Models Affected:

Wheel Loader WL350 up to SN 121575B80 Wheel Loader WL440 up to SN 121074B81

Subject:

Entry Steps (Part No. 17752494 and 17752197)

Symptoms:

There have been instances in cold weather where the entry steps have broken. This can result in someone falling and sustaining injury.

Cause:

Cold weather.

Remedy:

Replace existing entry steps. Machines after the serial numbers listed above will have the new steel steps.

Action:

Order Parts

WL350 Steel Entry Steps Part No. 22939797 - Quantity 2

WL350 Steel Entry Steps Part No. 22939805 - Quantity 2

WL440 Steel Entry Steps Part No. 22939805 - Quantity 4

- 2. Replace steps as soon as possible (The old step should be scraped)
- 3. Claims will be accepted for the above parts, 1 hour labor, actual travel time and mileage for each machine upgraded. Claims must reference CAMPAIGN NO. 06-6. Claims will be accepted until June 1, 2007.