



Technical Service Bulletin

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Number: PC

FOR INFORMATION ONLY

Date: June 6, 2007
Revised (10-12)

Subject: Retrofit Campaign - Start Solenoid

Symptoms: Compressor building air pressure at start-up, resulting in hard starting and premature coupling failure.

Models Affected: HP375WCU (B-11), XP375WCU (B-12), P425WCU (B-13)

Serial Numbers Affected: All serial numbers

Remedy: Order Kit CCN 44022556. See attachment.

Warranty Action: Reference Campaign 07-3