

## Portable Compressor

*Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.*

**PC-5-050**

**February 2, 1995**

**Revised (10-12)**

# JOHN DEERE ENGINE WATER PUMP SEAL (Information Only)

**MODELS AFFECTED:** All powered with John Deere 3179 and 4039 engines (3 and 4 cyl).

**SYMPTOMS:** Leaking engine water pump seal.

**REMEDY:** Leaking water pump lip seals on John Deere 4039 engine can be remedied by installing a mechanical seal.  
The mechanical seal became effective on new engines with engine serial number 175756.

**WARRANTY ACTION:** This bulletin for information purposes. Failures should be directed to John Deere for repair. This is not a campaign.