

Bulletin #: 2006-002 **Date:** 05/07/06


Product: ☒ Compressor ☐ Generator ☐ Tools

Subject: Foam replacement on 7-51 rear canopy

Models

7/51 SN 442041 – 442149

76 machines among the serial number range above have been fitted with not-to-specification insulation foam on the bottom of the fixed canopy. This foam can be recognised easily as it doesn't have a black protection layer on its surface, see photo. As a result dirt can accumulate and this foam will degrade quicker than the correct one.



We recommend replacing the foam with the correct foam panel CPN 54623335. Please advise how many parts you expect to replace in your territory in order for us to estimate the stock required.

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.