

## Technical Service Bulletin

<b>Bulletin #:</b>	LT-2006-002			<b>Date:</b>	16/05/06
<b>Product:</b>	<input type="checkbox"/> Compressor	<input type="checkbox"/> Generator	<input checked="" type="checkbox"/> Light Tower	<input type="checkbox"/> Tools	
<b>Subject:</b>	Battery terminal protection				

### Models

LT6

It has been noted that the protective cap on the battery positive terminal could move out of position during operation. This could lead to damage to the winch cable if it gets slightly loose and touches the terminal creating a shortcut. It is recommended to fit a wire tie around the cap as shown below to secure it in position.

The next version of the Light Tower will have the battery terminals swapped.



Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

**Revised (10-12)**