



Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

PC-12-010
May 6, 2003
Revised (10-12)

(GENSETS) FUEL LEAKS AROUND FUEL GAUGE

MODELS AFFECTED: G8 through G40

SYMPTOMS: Fuel leaking around Gauge Base

CAUSE: Improper seal

REMEDY: Replace flange seal, and reseal per supplied instructions

ACTION: Order seal and repair.
P/N 85490811 for seal, 85626364 for spacer if needed
P/N 85430007 for sealant

This is not a Campaign.