



*Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.*

**PC-12-011**  
**May 6, 2003**  
**Revised (10-12)**

## (GENSETS) INCORRECT PARTS LISTINGS ON MITSUBISHI ENGINES

**MODELS AFFECTED:** G8 through G40

**SYMPTOMS:** Parts listed in manual may not be correct for all engines.  
 Incorrect parts ordered

**CAUSE:** Production changes

**REMEDY:** Identify the proper engine model by looking for model number on top of valve cover.

**ACTION:** . Please use the Mitsubishi parts listings at the rear of the Manual, Using the corresponding line in the manual, find the Correct Mitsubishi part number and order the needed parts.

The 1 represents the correct part number for this engine model

Note the \* is showing this part number is not compatible to this engine model number

61-04-02 カハナ  
 GOVERNOR (FOR S4Q2)

- 47 -

見出 番号 REF. NO.	部品番号 PART NO.	部品名称 および 記事・仕様記号 PART NAME & DESCRIPTION	形大 個数 MODEL&QTY		適用号機 APPLICABLE SERIAL NO. FROM~ ->UPTO	注 RE MARKS
			S4Q	S4Q2		
142	94915-00210	SEAL,OIL	.	1		A
143	09107-11930	LEVER,ADJUSTING	.	1		
144	94904-71190	BOLT,W/WASHER	.	1		A
145	09109-40060	CAP,LEVER	.	1		
146	09109-01030	LEVER STOP	.	1		