

Technical Service Bulletin



Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Number: PC12-042

Date: Jan. 5, 2009
Revised (10-12)

Subject: Hard starting of Honda powered equipment

Symptoms: Unit will not start, or is hard to start when new.

Models Affected: ALL HONDA POWERED EQUIPMENT IN DEALER STOCK

Remedy:

Remove and clean the carburetor and carburetor bowl on engine for all new units in stock, this will require cleaning only. Do not replace the carb, as it only requires cleaning out as old fuel has collected in the bowl during testing and storage

Warranty:

Warranty claims will be accepted for 1 hour labor per machine until June 1, 2009. Claims will only be paid for new unsold units in Dealer stock.