

Doosan Infracore International
1293 Glenway Drive
Statesville, N.C. 28625



Doosan Infracore
Portable Power

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

TECHNICAL SERVICE BULLETIN

Number: PC12-044

Date: Feb 6, 2009
Revised (10-12)

Subject: Radiators for Lightsource and L6.

Models Affected:

Lightsource	L6	L8
Serial #	Serial #	Serial #
395683ULRC13	395694ULRC45	396690UAS819

Remedy:

When ordering radiators for units prior to the serial number break use CCN 36888451, for units after the serial number break please use CCN 23083405.

Warranty:

This is not a Campaign and is for information only.

