



Technical Service Bulletin

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.


Number: PC13-006

Date: June 6, 2007

Revised (10-12)

Subject: Cooler Mounts on ZX75 and ZX125 Excavators (Information Only)

During installation, the cooler mounts may become twisted and cause premature failure. To prevent this from happening, make a line lengthwise on the mount with a straight edge prior to installation. Install the mount. Use a strap wrench to hold the mount while tightening the fasteners. After tightening both sides of the mount, the line you made on the mount should be straight.



Correct

Wrong

**Cooler Mounts part#
part# 17762188**

