

Portable Compressor

PC-8-000

6-22-04

XHP INDEX

PC-8-001	08-04-80	Air Cleaner, Assemblies for XHP750-SGM, XHP750-W-GM, HP850-W-GM, XP900-W-GM and P1100-WW-GM Units
PC-8-002	08-04-80	Field Replacement of D750, D750S, XHP750SGM, and XHP750WGM Air Ends
PC-8-003	10-15-82	Front Seal Air Supply for D750, and XHP750/200 OF
PC-8-004	4-8-03 revised	High Pressure Airend Lubricants – Mocksville Built Units.
PC-8-005	07-11-86 Cancelled 9-16-99)	Compressor Oil for XHP-OF
PC-8-006	01-27-87	Oil Strainer Element Maintenance
PC-8-007	06-28-88	Plugged Oil Galleys in Airend on the XHP750-S-CAT (HR-2 Airend) on Mocksville Built Units.
PC-8-008	05-26-93 (Revised)	HR2 (XHP) Airend “Burp” or overheating. Any XHP Portable Compressor, Mocksville Built Units.
PC-8-009	01-13-93 (Revised)	Venting of Interstage Relief Valve. Any XHP Portable Compressor so equipped. Mocksville Built Units.
PC-8-010	03-17-93	HR2 (XHP) Airend Bearing Oil Tube Failure. Any XHP Portable Compressor. Mocksville Built Units.

PC8-011	02-07-95 10-16-95 (Update) 11-07-95 (Update) 07-01-97 (Update)	HR2 Airend Steel Tubing.
PC8-012	08-15-96 (revised 05-05-99)	XHP750/825/900 (HR2) Shaft Seal Mocksville Built Units.
PC8-013	04-14-97	Fire Hazard caused by Leaking Engine Exhaust Elbow.
PC8-014	04-03-98 (cancelled) (refer to PC8-012 dated 5-5-99)	XHP Airend (HR2) Shaft Seal
PC8-015	07-09-98	Discharge Hose
PC8-016	05-06-99	Fan Contact to Orifice Ring
PC8-017	05-06-99	Pressure Reducing Valve on Customer One Products
PC8-018	05-06-99	Cold Weather Operation of Hydraulic Driven Fans
PC8-019	07-15-99	SCAT Oil Cooling & Air After Cooling System
PC8-020	5-6-03	XHP505 Fluid to be replaced
PC8-021	6-22-04	Compressor Fluid Level