



Technical Service Bulletin

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Number: PC12-029

Date: Oct. 18, 2006 **Revised (10-12)**

Subject: Incorrectly crimped cabling on light tower upper and center tower boom

MODELS AFFECTED:

Models	Serial Number Range
Lightsource	367811 to 374084
L6	366208 to 391945
L8	368427 to 371195

The above models were fitted with an incorrectly crimped upper and center tower boom cables. See attached serial number list for all affected units.

SYMPTOMS:

Broken cable.

REMEDY:

Reference the attached ser# list for affected units and replace incorrect cables with IR CPN 22965404. We will allow 1 hr labor to make the repair. Submit warranty and reference Campaign number 06-8 for this repair. Destroy all old cables.

371017UEQC13	370607UEQC13	374042UGQC13	370030UDQC13	369285UCQ789
371021UEQC13	370608UEQC13	374043UGQC13	370031UDQC13	369286UCQ789
373421UFQC13	370609UEQC13	374051UGQC13	371623UEQC13	368708UCQ789
367884UCQ789	370610UEQC13	374052UGQC13	371625UEQC13	368713UCQ789
296736UAT822	372736UFQC13	374056UGQC13	371626UEQC13	368730UCQ789
369211UCQ789	372737UFQC13	374057UGQC13	373404UFQC13	368731UCQ789
369212UCQ789	372738UFQC13	374058UGQC13	373405UFQC13	368734UCQ789
369259UCQ789	372739UFQC13	374059UGQC13	373406UFQC13	368735UCQ789
369260UCQ789	372740UFQC13	374060UGQC13	373407UFQC13	372518UFQC13
369261UCQ789	372741UFQC13	374061UGQC13	373408UFQC13	372519UFQC13
369262UCQ789	372742UFQC13	374062UGQC13	370058UDQC13	372520UFQC13
369263UCQ789	372743UFQC13	374063UGQC13	370059UDQC13	372521UFQC13
369264UCQ789	370557UDQC13	374067UGQC13	370060UDQC13	372522UFQC13
369265UCQ789	370562UDQC13	374068UGQC13	370061UDQC13	372523UFQC13
369266UCQ789	373202UFQC13	374069UGQC13	370185UDQC13	372524UFQC13
368430UCQ789	373203UFQC13	374070UGQC13	370186UDQC13	372525UFQC13
368431UCQ789	370187UDQC13	374071UGQC13	366208UQA822	371009UEQC13
369287UCQ819	370188UDQC13	374072UGQC13	366209UQA822	371010UEQC13
369289UCQ819	369208UCQ789	374073UGQC13	368740UCQ789	371011UEQC13
369291UCQ819	372538UFQ822	374074UGQC13	368741UCQ789	371012UEQC13
369293UCQ819	372539UFQ822	374075UGQC13	368742UCQ789	371013UEQC13
369295UCQ819	371944UEQC13	374076UGQC13	368743UCQ789	371014UEQC13
369288UCQ819	372485UFQC13	374077UGQC13	368744UCQ789	371015UEQC13
369290UCQ819	372486UFQC13	374078UGQC13	368745UCQ789	371016UEQC13
369292UCQ819	372487UFQC13	374079UGQC13	369269UCQ789	373432UFQC13
369294UCQ819	368746UCQ789	374080UGQC13	369271UCQ789	368706UCQ789
373422UFQC13	369206UCQ789	374081UGQC13	371622UEQC13	368707UCQ789
373424UFQC13	369209UCQ789	374082UGQC13	371624UEQC13	368709UCQ789
373428UFQC13	369210UCQ789	374083UGQC13	371627UEQC13	368711UCQ789
368726UCQ789	367875UCQ822	373409UFQC13	371628UEQC13	368712UCQ789
368727UCQ789	367876UCQ822	373411UFQC13	371629UEQC13	370189UDQC13
369213UCQ789	367877UCQ822	373412UFQC13	369395UDQ789	370593UEQC13
369277UCQ13	367878UCQ822	373413UFQC13	368743UCQ789	368716UCQ789
369278UCQ13	367879UCQ822	371938UEQC13	369217UCQ819	369717UDQ789
369279UCQ13	367880UCQ822	369267UCQ789	369218UCQ819	369718UDQ789
369280UCQ13	368747UCQ822	371020UEQC13	369219UCQ819	369719UDQ789
369281UCQ13	368748UCQ822	371022UEQC13	369220UCQ819	369720UDQ789
369282UCQ13	368749UCQ822	371023UEQC13	369221UCQ819	369721UDQ789
373202UFQC13	368750UCQ822	371024UEQC13	369222UCQ819	369722UDQ789
373204UFQC13	368751UCQ822	373674UGQC13	369223UCQ819	369723UDQ789
373205UFQC13	369715UDQ769	373676UGQC13	369224UCQ819	369724UDQ789
373206UFQC13	369716UDQ769	373677UGQC13	371018UEQC13	369915UDQC13
373207UFQC13	369725UDQ769	373678UGQC13	372760UFQC13	369916UDQC13
373208UFQC13	371226UEQC13	373679UGQC13	372761UFQC13	369917UDQC13
373221UFQC13	371227UEQC13	373680UGQC13	368429UCQ789	369918UDQC13
369283UCQ13	371228UEQC13	373681UGQC13	372458UFQC13	369919UDQC13
369284UCQ13	371229UEQC13	373682UGQC13	368444UCQ789	369920UDQC13
371260UEQC13	371230UEQC13	373710UGQC45	368447UCQ789	369921UDQC13
371261UEQC13	371231UEQC13	369770UDQ789	368448UCQ789	369922UDQC13
371262UEQC13	371232UEQC13	373993UGQC13	368451UCQ789	371618UEQC13
371263UEQC13	371233UEQC13	305021UIJ729	369205UCQ789	371619UEQC13
371264UEQC13	368740UCQ789	367897UCQ789	369215UCQ789	370596UEQC13
371265UEQC13	369270UCQ789	367904UCQ789	370051UDQC13	370597UEQC13
373766UGQC13	369272UCQ789	367909UCQ789	370052UDQC13	370598UEQC13
373767UGQC13	369274UCQ789	367911UCQ789	370053UDQC13	371951UEQC13
373768UGQC13	368435UCQ789	368389UDQ789	370054UDQC13	371952UDQC13
373769UGQC13	370191UDQC13	368390UDQ789	370055UDQC13	368427UCQ819
373770UGQC13	371930UEQC13	368392UDQ789	370056UDQC13	373431UFQC13
367830UBQ789	372749UFQC13	368393UDQ789	370057UDQC13	373433UFQC13
368391UDQ789	371635UEQC13	368452UCQ789	370062UDQC13	373434UFQC13
374002UGQC13	371637UEQC13	368717UCQ789	370063UDQC13	373435UFQC13
374003UGQC13	371639UEQC13	368718UCQ789	370064UDQC13	373436UFQC13
374004UGQC13	371641UEQC13	368720UCQ789	370190UDQC13	373222UFQC13
374005UGQC13	371643UEQC13	368721UCQ789	370192UDQC13	373616UFQC13
374006UGQC13	371645UEQC13	368722UCQ789	371019UEQC13	373632UFQC13
374007UGQC13	371648UEQC13	369202UCQ789	369273UCQ789	373651UFQC13
374008UGQC13	371650UEQC13	369203UCQ789	373231UFQC13	373652UFQC13
374009UGQC13	371652UEQC13	369204UCQ789	373232UFQC13	373653UFQC13
369190UCQ789	371654UEQC13	369205UCQ789	373233UFQC13	373654UFQC13
369191UCQ789	371636UEQC13	369214UCQ789	373234UFQC13	373655UFQC13
367820UBQ789	371638UEQC13	369216UCQ789	373235UFQC13	367885UCQ789
367821UBQ789	371640UEQC13	369388UDQ789	373236UFQC13	367887UCQ789
371939UEQC13	371642UEQC13	369394UDQ789	373237UFQC13	368709UCQ789
371940UEQC13	371644UEQC13	369396UDQ789	373238UFQC13	368723UCQ789
368433UCQ789	371646UEQC13	369401UDQ789	373671UGQC13	368724UCQ789