



**Technical Service Bulletin**

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

**Number:** PC12-033

**Date:** March 13, 2007  
**Revised (10-12)**

**SUBJECT:**

Engine hunting and smoking issues on Powersource G60 generators..

**MODELS AFFECTED:**

Serial numbers affected
360417 thru 373030

**SYMPTOMS:**

Instability issue on units during cold start and restart.

**REMEDY:**

Order kit 44018695 and use the provided software and cable to correct the programing in the engine control module on each machine in the above serial number range, per the included instructions.

THIS IS A CAMPAIGN. Warranty claims will be accepted for 1 hour labor per machine. Warranty claim must reference campaign 06-11.

360417UHPB55	364874ULPB55	369307UCQB55
360418UHPB55	364875ULPB55	369308UCQB55
360419UHPB55	364876ULPB55	369309UCQB55
362841UJPB55	364877ULPB55	369310UCQB55
362842UJPB55	365370UAQB55	369311UCQB55
362843UJPB55	365371UAQB55	370369UDQB55
362844UJPB55	365780UAQB55	370370UDQB55
362845UJPB55	365781UAQB55	370371UDQB55
362846UJPB55	366056UAQB55	370372UDQB55
362847UJPB55	366057UAQB55	370372UDQB55
362848UJPB55	366296UAQB55	370373UDQB55
362849UJPB55	366710UBQB55	370374UDQB55
362850UJPB35	366711UBQB55	370375UDQB55
364539ULPB55	366712UBQB55	370376UDQB55
364808ULPB55	366735UBQB55	370377UDQB55
364844ULPB55	367037UBQB55	370379UDQB55
364845ULPB55	367038UBQB55	370380UDQB55
364846ULPB55	367039UBQB55	370382UDQB55
364847ULPB55	369296UCQB55	370383UDQB55
364848ULPB55	369297UCQB55	370384UDQB55
364849ULPB55	369298UCQB55	370385UDQB55
364850ULPB55	369299UCQB55	371109UEQB55
364851ULPB55	369300UCQB55	371110UEQB55
364852ULPB55	369301UCQB55	371111UEQB55
364853ULPB55	369302UCQB55	371112UEQB55
364853ULPB55	369303UCQB55	371343UEQB55
364854ULPB55	369304UCQB55	371907UEQB55
364855ULPB55	369305UCQB55	371908UEQB55
364856ULPB55	369306UCQB55	371909UEQB55
364857ULPB55	373027UFQB55	372734UFQB55
372779UFQB55	373030UFQB55	372735UFQB55
372780UFQB55	372776UFQB55	
373025UFQB55	372777UFQB55	
373026UFQB55	372778UFQB55	