



Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

Technical Service Bulletin

PC-7-035

July 15, 2005

Revised (10-12)

IMMEDIATE ACTION REQUIRED

Subject: Valve plate coming loose from valve stem in unloader valve Assembly 36734515. Valve must be checked to assure it is tight to stem.

Models Affected:

XP750DWCU	XP825DWCU	HP935WCU
HP750DWCU	MHP825WCU	XP1060WIR
VHP750BWCU		

Serial number Range: 351696 through 358541 (complete list included)

Symptoms: Oil and air may be discharged through the compressor air filter when the machine is stopped. **CAN PRESENT A SAFETY AND/OR FIRE HAZARD.**

Cause: Valve vibrates loose from the valve stem.

Remedy: All machines must have the unloader valve inspected to determine if the valve and stem connection is tight. Perform the inspection per the following instructions:

SERIAL_NUMBER	MOD_FAMILY
351696ULO259	HP935WCU
351697UKOA16	XP750WCU
351698UKOA16	XP750WCU
351699ULO18	XP825WCU
351820ULO18	XP825WCU
351827ULO259	HP935WCU
351969UAP259	HP935WCU
351970UAP259	HP935WCU
351971UAP259	HP935WCU
351973UAPA18	XP825DWCU
351974UAPA18	XP825WCU
351975UAPA18	XP825WCU
351976UAPA18	XP825WCU
352168UAP259	HP935WCU
352169UAP259	HP935WCU
352170UAP259	HP935WCU
352171UAP259	HP935WCU
352172UAPA16	XP750DWCU
352173UAPA16	XP750DWCU
352174UAPA18	XP825DWCU
352175UAPA18	XP825DWCU
352176UAPA18	XP825DWCU
352340UAPA16	XP750DWCU
352341UAPA16	XP750DWCU
352342UAPA18	XP825DWCU
352343UAPA18	XP825DWCU
352344UAPA18	XP825DWCU
352345UAPA18	XP825DWCU
352483UAP259	HP935WCU
352484UAP259	HP935WCU
352590UAPA18	XP825DWCU
352591UAPA18	XP825DWCU
352592UAPA18	XP825DWCU
352593UAPA18	XP825DWCU
352594UAPA18	XP825DWCU
352595UAPA18	XP825WCU
352751UAP259	HP935WCU
352752UAP259	HP935WCU
352756UAPA17	HP750DWCU

SERIAL_NUMBER	MOD_FAMILY
352757UAPA17	HP750DWCU
352758UAPA16	XP750DWCU
352759UAPA16	XP750DWCU
352760UAPA16	XP750DWCU
352761UAPA16	XP750DWCU
352762UAPA16	XP750DWCU
352763UAPA16	XP750DWCU
352764UAPA16	XP750WCU
353148UBPA16	XP750DWCU
353149UBPA18	XP825WCU
353387UBPA16	XP750DWCU
353388UBPA16	XP750DWCU
353389UBPA16	XP750DWCU
353390UBPA16	XP750DWCU
353391UBPA16	XP750WCU
353392UBPA16	XP750DWCU
353393UBPA16	XP750DWCU
353394UBPA16	XP750DWCU
353395UBPA16	XP750DWCU
353396UBPA16	XP750DWCU
353520UBP824	HP935WCU
353521UBPB24	HP935WCU
353585UBPB24	HP935WCU
353586UBPB24	HP935WCU
353590UBPA16	XP750DWCU
353591UBPA16	XP750DWCU
353592UBPA16	XP750DWCU
353593UBPA16	XP750DWCU
353594UBPA16	XP750DWCU
353595UBPA16	XP750WCU
353596UBPA16	XP750WCU
353597UBPA16	XP750WCU
353688UBPA16	XP750WCU
353750UBPB24	HP935WCU
353751UBPB24	HP935WCU
353752UBPB24	HP935WCU
353753UBPB24	HP935WCU
353754UBPB24	HP935WCU
353758UBPA17	HP750DWCU

SERIAL_NUMBER	MOD_FAMILY
353759UBPA17	HP750DWCU
353760UBPA17	HP750DWCU
353761UBPA17	HP750DWCU
353762UBPA18	XP825DWCU
353763UBPA18	XP825DWCU
353764UBPA18	XP825DWCU
353765UBPA18	XP825DWCU
353766UBPA18	XP825DWCU
353767UBPA18	XP825DWCU
353768UBPA18	XP825DWCU
353769UBPA18	XP825DWCU
353770UBPA18	XP825WCU
354064UCPB30	HP935WCU
354065UCPB30	HP935WCU
354066UCPB30	HP935WCU
354067UCPB30	HP935WCU
354068UCPB30	HP935WCU
354069UCPB30	HP935WCU
354070UCPB30	HP935WCU
354074UCPA17	HP750DWCU
354075UCPA17	HP750DWCU
354076UCPA17	HP750DWCU
354077UCPA17	HP750DWCU
354078UCPA17	HP750DWCU
354079UCPA17	HP750DWCU
354080UCPA17	HP750DWCU
354081UCPA17	HP750DWCU
354082UCPA17	HP750DWCU
354083UCPA17	HP750DWCU
354084UCPA17	HP750DWCU
354085UCPA18	XP825DWCU
354087UCPA18	XP825DWCU
354088UCPA18	XP825DWCU
354089UCPA18	XP825WCU
354090UCPA18	XP825WCU
354404UCPB24	HP935WCU
354405UCPB24	HP935WCU
354406UCPB24	HP935WCU
354407UCPB24	HP935WCU

SERIAL_NUMBER	MOD_FAMILY
354412UCPA16	XP750DWCU
354413UCPA16	XP750DWCU
354414UCPA16	XP750DWCU
354415UCPA16	XP750DWCU
354416UCPA16	XP750DWCU
354417UCPA16	XP750DWCU
354418UCPA16	XP750WCU
354897UCPB24	HP935WCU
354898UCPB24	HP935WCU
354899UCPB24	HP935WCU
354900UCPB25	XP1060WIR
354901UCPB25	XP1060WIR
354902UCPA17	HP750WCU
354903UCPA17	HP750WCU
354904UCPA17	HP750WCU
354905UCPA17	HP750DWCU
354906UCPA17	HP750WCU
354907UCPA17	HP750DWCU
354908UCPA17	HP750DWCU
354909UCPA18	XP825DWCU
354910UCPA18	XP825WCU
354911UCPA18	XP825WCU
354912UCPA18	XP825WCU
354915UCPA16	XP750WCU
354969UCPA18	XP825DWCU
354970UCPA18	XP825DWCU
354971UCPA18	XP825DWCU
354972UCPA18	XP825DWCU
354973UCPA18	XP825DWCU
354974UCPA18	XP825DWCU
355113UCPB30	HP935WCU
355114UCPB30	HP935WCU
355115UCPB30	HP935WCU
355116UCPB30	HP935WCU
355117UCPB30	HP935WCU
355118UCPB30	HP935WCU
355119UCPB30	HP935WCU
355120UCPB30	HP935WCU
355130UCPA16	XP750DWCU

PC-8-035
July 13, 2005

SERIAL_NUMBER	MOD_FAMILY
355131UCPA16	XP750DWCU
355132UCPA16	XP750DWCU
355133UCPA16	XP750DWCU
355134UCPA17	HP750DWCU
355135UCPA17	HP750DWCU
355136UCPA17	HP750DWCU
355137UCPA17	HP750DWCU
355138UCPA17	HP750DWCU
355139UCPA17	HP750DWCU
355140UCPA17	HP750DWCU
355141UCPA17	HP750DWCU
355142UCPA17	HP750DWCU
355143UCPA18	XP825WCU
355411UDPA16	XP750WCU
355412UDPA16	XP750DWCU
355413UDPA16	XP750DWCU
355415UDPA18	XP825DWCU
355416UDPA18	XP825DWCU
355417UDPA18	XP825DWCU
355418UDPA18	XP825DWCU
355419UDPA18	XP825DWCU
355420UDPA18	XP825DWCU
355421UDPA18	XP825WCU
355422UDPA18	XP825WCU
355423UDPA18	XP825WCU
355424UDPA18	XP825WCU
355425UDPA18	XP825WCU
355426UDPA18	XP825WCU
355427UDPA18	XP825WCU
355428UDPA18	XP825DWCU
355429UDPA18	XP825WCU
355430UDPA18	XP825WCU
355631UDPB24	HP935WCU
355632UDPB22	VHP750WIR
355638UDPA17	HP750DWCU
355639UDPA17	HP750DWCU
355640UDPA17	HP750DWCU
355641UDPA17	HP750DWCU
355642UDPA17	HP750DWCU
355643UDPA17	HP750DWCU

SERIAL_NUMBER	MOD_FAMILY
355644UDPA17	HP750DWCU
355645UDPA17	HP750DWCU
355646UDPA17	HP750DWCU
355647UDPA17	HP750DWCU
355648UDPA17	HP750WCU
355649UDPA16	XP750DWCU
355650UDPA18	XP825WCU
355651UDPA17	HP750DWCU
355652UDPA17	HP750DWCU
355653UDPA17	HP750DWCU
355654UDPA17	HP750DWCU
355655UDPA17	HP750DWCU
355656UDPA17	HP750DWCU
355657UDPA17	HP750DWCU
355658UDPA17	HP750DWCU
355659UDPA17	HP750DWCU
355660UDPA17	HP750DWCU
355976UDPB18	VHP750BWCAT
355977UDPB18	VHP750BWCAT
355978UDPB18	VHP750BWCAT
355979UDPB25	XP1060WIR
355980UDPB25	XP1060WIR
355986UDPA18	XP825DWCU
356105UDPA16	XP750WCU
356106UDPA16	XP750DWCU
356107UDPA16	XP750DWCU
356108UDPA16	XP750WCU
356110UDPA18	XP825DWCU
356111UDPA18	XP825DWCU
356112UDPA18	XP825DWCU
356113UDPA18	XP825DWCU
356114UDPA18	XP825DWCU
356115UDPA18	XP825DWCU
356302UDPB24	HP935WCU
356303UDPB24	HP935WCU
356304UDPB30	HP935WCU
356305UDPB30	HP935WCU
356306UDPB30	HP935WCU
356307UDPB30	HP935WCU
356308UDPB23	MHP825WCU

PC-8-035
July 13, 2005

SERIAL_NUMBER	MOD_FAMILY
356497UEPB30	HP935WCU
356498UEPB30	HP935WCU
356499UEPB30	HP935WCU
356500UEPB30	HP935WCU
356501UEPB30	HP935WCU
356502UEPB30	HP935WCU
356503UEPB30	HP935WCU
356504UEPB30	HP935WCU
356505UEPB30	HP935WCU
356506UEPB30	HP935WCU
356507UEPB30	HP935WCU
356508UEPB24	HP935WCU
356516UEPA16	XP750DWCU
356517UEPA18	XP825DWCU
356518UEPA18	XP825DWCU
356519UEPA18	XP825DWCU
356744UEPB24	HP935WCU
356745UEPB23	MHP825WCU
356746UEPB23	MHP825WCU
356747UEPB23	MHP825WCU
356748UEPB23	MHP825WCU
356749UEPB23	MHP825WCU
356754UEPA17	HP750DWCU
356755UEPA17	HP750DWCU
356756UEPA17	HP750DWCU
356757UEPA17	HP750DWCU
356758UEPA17	HP750DWCU
356759UEPA17	HP750DWCU
356760UEPA17	HP750DWCU
356764UEPA18	XP825DWCU
356765UEPA18	XP825DWCU
357146UEPB23	MHP825WCU
357147UEPB23	MHP825WCU
357148UEPB23	MHP825WCU
357149UEPB23	MHP825WCU
357150UEPB23	MHP825WCU
357156UEPA16	XP750WCU
357157UEPA16	XP750DWCU
357158UEPA16	XP750DWCU
357159UEPA16	XP750DWCU

SERIAL_NUMBER	MOD_FAMILY
357160UEPA16	XP750DWCU
357161UEPA16	XP750DWCU
357162UEPA18	XP825DWCU
357163UEPA18	XP825DWCU
357164UEPA18	XP825DWCU
357165UEPA18	XP825DWCU
357438UEPA17	HP750DWCU
357439UEPA17	HP750DWCU
357440UEPA17	HP750DWCU
357441UEPA17	HP750DWCU
357443UEPA16	XP750DWCU
357444UEPA16	XP750DWCU
357445UEPA16	XP750DWCU
357446UEPA16	XP750DWCU
357447UEPA18	XP825WCU
357448UEPA18	XP825DWCU
357527UEPB30	HP935WCU
357528UEPB30	HP935WCU
357541UEPA17	HP750DWCU
357542UEPA17	HP750DWCU
357543UEPA17	HP750DWCU
357544UEPA17	HP750DWCU
357545UEPA17	HP750DWCU
357546UEPA17	HP750DWCU
357547UEPA18	XP825DWCU
357548UEPA18	XP825DWCU
357808UFPA17	HP750DWCU
357809UFPA17	HP750DWCU
357810UFPA17	HP750DWCU
357811UFPA17	HP750DWCU
357812UFPA17	HP750DWCU
357813UFPA17	HP750DWCU
357814UFPA17	HP750DWCU
357815UFPA17	HP750DWCU
357816UFPA17	HP750DWCU
357817UFPA17	HP750DWCU
357818UFPA17	HP750DWCU
357819UFPA17	HP750DWCU
357827UFPA16	XP750WCU
358145UFPA17	HP750DWCU

PC-8-035
July 13, 2005

SERIAL_NUMBER	MOD_FAMILY
358143UFPB24	HP935WCU
358144UFPA17	HP750DWCU
358146UFPA18	XP825WCU
358147UFPA18	XP825WCU
358301UFPA17	HP750DWCU

SERIAL_NUMBER	MOD_FAMILY
358302UFPA17	HP750DWCU
358303UFPA17	HP750DWCU
358304UFPA17	HP750DWCU
358541UFPA17	HP750WCU