

Portable Compressor

Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Doosan Company or the products of either.

PC8-020
May 6, 2003
Revised (10-12)

XHP505 COMPRESSOR FLUID TO BE REPLACED

Ingersoll-Rand XHP505 Compressor Fluid has been the factory fill fluid for all portable compressors above 300 psi since 1999.

XHP505 is being replaced by XHP605 for factory fill beginning in April 2003.

XHP605 is a direct replacement for XHP505 and is required to maintain the limited extended airend warranty for those applications previously using XHP505.

XHP405 is also a direct replacement for XHP505 in those applications where limited extended airend warranty is not desired. The use of XHP405 does not provide extended airend warranty coverage.

XHP405 and 605 provide improvements over XHP505 primarily as it pertains to the fluids ability to be separated from the air during the compression process. XHP405 and 605 provide enhanced air release and foam characteristics. Both new fluids are compatible with XHP505 therefore stocks of XHP505 may be used and mixed with XHP605 or XHP405.

Following is comparison of the fluids:

OLD FLUID	NEW FLUID	FACTORY FILL	EXTENDED WARRANTY AVAILABLE	COMPATIBLE WITH XHP505	COLOR
XHP505	XHP605	YES	YES	YES	CLEAR
XHP505	XHP405	NO	NO	YES	AMBER

Following is a listing of the quantities available from Ingersoll-Rand:

Fluid	5 Gal (3.8 litres)	55 Gal (208.2 litres)	220 Gal (836 litres)
XHP605	22252076	22252050	22252068
XHP405	22252126	22252100	22252118